

RENATA

for **PESEUX** (suite)

•1689	10 $\frac{1}{2}$ '''	7020	ord. & Inca Glucydur sans vis
•1689	10 $\frac{1}{2}$ '''	7024	ord. & Inca Glucydur sans vis = 7020
•1689	11 $\frac{1}{2}$ '''	7030	ord. & Inca Glucydur sans vis = 7020
•1689	11 $\frac{1}{2}$ '''	7034	ord. & Inca Glucydur sans vis = 7020
•1681	10 $\frac{1}{2}$ '''	7040	ord. & Inca sans vis
•1681	10 $\frac{1}{2}$ '''	7046	ord. & Inca sans vis = 7040
•1681	11 $\frac{1}{2}$ '''	7050	ord. & Inca sans vis = 7040
•1681	11 $\frac{1}{2}$ '''	7056	ord. & Inca sans vis = 7040
•1680	10 $\frac{1}{2}$ '''	7060	ord. & Inca sans vis
•1680	10 $\frac{1}{2}$ '''	7066	ord. & Inca sans vis = 7060
•1680	11 $\frac{1}{2}$ '''	7070	ord. & Inca sans vis = 7060
•1680	11 $\frac{1}{2}$ '''	7076	ord. & Inca sans vis = 7060

for **PHENIX**

660	8 $\frac{3}{4}$ '''	89	
660	8 $\frac{3}{4}$ '''	93	= 89
649	10 $\frac{1}{2}$ '''	110	
649	10 $\frac{1}{2}$ '''	115	= 110
649	10 $\frac{1}{2}$ '''	116	= 110
618	10 $\frac{1}{2}$ '''	130	ord. & Inca
618	10 $\frac{1}{2}$ '''	132	ord. & Inca = 130
618	10 $\frac{1}{2}$ '''	140	ord. & Inca = 130
724	13'''	160	
1462	10 $\frac{1}{2}$ '''	180	
1463	10 $\frac{1}{2}$ '''	180	Inca
1462	10 $\frac{1}{2}$ '''	190	= 180
1463	10 $\frac{1}{2}$ '''	190	Inca = 180 Inca
1328	5 $\frac{1}{4}$ '''	230	ord. & Inca
814	5 $\frac{1}{4}$ '''	514	

for **PIERCE / LEVY / ROCAIL**

640	5 $\frac{1}{4}$ '''	59	
640	5 $\frac{1}{4}$ '''	59	Inca
283	10 $\frac{1}{2}$ '''	100	
597	10 $\frac{1}{2}$ '''	100	Inca
283	10 $\frac{1}{2}$ '''	103	= 100
597	10 $\frac{1}{2}$ '''	103	Inca = 100 Inca
694	10 $\frac{1}{2}$ '''	105	
694	10 $\frac{1}{2}$ '''	105	Inca
370	12'''	132	
395	13'''	134	
369	5'''	516	

• annulaire, schraubenlos, screwless, sin tornillos

for **PIERCE / LEVY / ROCAIL** (suite)

434	7 $\frac{3}{4}$ -11'''	711	
434	8 $\frac{3}{4}$ -12'''	812	= 711
284	8 $\frac{3}{4}$ '''	861	

for **POLJOT**

•1598 3017 sans vis

for **PRECIMAX / HELIOS / NPX**

823	10 $\frac{1}{2}$ '''	250	
285	10 $\frac{1}{2}$ '''	400	
285	10 $\frac{1}{2}$ '''	450	= 400
389	5 $\frac{1}{4}$ '''	500	
410	6 $\frac{3}{4}$ -8'''	600	

for **PUW**

371	5 $\frac{1}{4}$ '''	49	ord. & KIF
371	5 $\frac{1}{4}$ '''	49	SC ord. & KIF = 49
1190	11 $\frac{1}{2}$ '''	54	Unishock
1190	11 $\frac{1}{2}$ '''	54	A Unishock = 54 Unishock
1190	11 $\frac{1}{2}$ '''	54	B Unishock = 54 Unishock
1190	11 $\frac{1}{2}$ '''	55	Unishock = 54 Unishock
1190	11 $\frac{1}{2}$ '''	57	Unishock = 54 Unishock
1190	11 $\frac{1}{2}$ '''	59	Unishock = 54 Unishock
481	10 $\frac{1}{2}$ '''	60	ord. Inca KIF SSR
481	10 $\frac{1}{2}$ '''	61	ord. Inca KIF SSR = 60
481	10 $\frac{1}{2}$ '''	61	S ord. Inca KIF SSR = 60
481	10 $\frac{1}{2}$ '''	63	ord. Inca KIF SSR = 60
481	10 $\frac{1}{2}$ '''	65	ord. Inca KIF SSR = 60
517	5'''	70	
1154	5'''	70	Inca
•1410	5'''	70	Inca sans vis
517	5'''	73	= 70
1154	5'''	73	Inca = 70 Inca
•1410	5'''	73	Inca s. vis = 70 Inca
•1410	5'''	74	Inca s. vis = 70 Inca
993	6 $\frac{3}{4}$ -8'''	80	
•1271	11 $\frac{1}{2}$ '''	260	ord. & Inca sans vis
•1271	11 $\frac{1}{2}$ '''	261	ord. & Inca s. vis = 260
•1459	11 $\frac{1}{2}$ '''	360	stossges. sans vis
•1459	11 $\frac{1}{2}$ '''	361	stossges. sans vis = 360 st.
•1459	11 $\frac{1}{2}$ '''	363	stossges. sans vis = 360 st.
486	8 $\frac{3}{4}$ -12'''	500	
486	10 $\frac{1}{2}$ '''	501	= 500

RENATA – El más importante productor del mundo de volantes regulados para la reparación

RENATA

for PUW (suite)

1190	11 1/2'''	570	Unishock = 54 Unishock
1190	11 1/2'''	590	Unishock = 54 Unishock
•1684	5 1/2'''	1075	ord. & Inca sans vis
•1271	11 1/2'''	1260	ord. & Inca s. vis = 260
•1271	11 1/2'''	1261	ord. & Inca s. vis = 260
•1459	11 1/2'''	1360	stosses. sans vis = 360 st.
•1459	11 1/2'''	1361	stosses. sans vis = 360 st.
•1459	11 1/2'''	1363	stosses. sans vis = 360 st.

for RAYVILLE / BLANCPAIN

1011	5'''	49
------	------	----

for RECONVILIER / SHR

286	5 1/4'''	11
287	10 1/2'''	12
287	11 1/2'''	120 = 12
286	5 1/4'''	1210 = 11
994	10 1/2'''	2320
994	10 1/2'''	2321 = 2320

for RECORD

413	13'''	022 K
288	12 1/2'''	022-18 Glucydur
289	16'''	25
289	16'''	26 = 25
407	8 3/4'''	102
407	8 3/4'''	103 = 102
414	10 1/2'''	106
414	10 1/2'''	107 = 106
290	5 1/4'''	108
290	5 1/4'''	109 = 108
445	8 3/4-12'''	110
445	8 3/4-12'''	111 = 110
445	8 3/4-12'''	112 = 110
445	8 3/4-12'''	113 = 110
445	8 3/4-12'''	114 = 110
291	7 3/4-11'''	116 Glucydur
291	7 3/4-11'''	117 Glucydur = 116 Glucydur
291	7 3/4-11'''	118 Glucydur = 116 Glucydur
291	7 3/4-11'''	120 Glucydur = 116 Glucydur
292	9 3/4'''	160
292	9 3/4'''	170 = 160
292	9 3/4'''	174 = 160

for RECTA / MV

839	8 3/4'''	C 3
944	8 3/4'''	C 3 Breguet
293	10 1/2'''	F
1007	6 3/4-8'''	M 21/1
1084	5'''	N/2
1183	5 1/4'''	H 3 Glucydur
1129	10 1/2'''	81/1 Glucydur

for REGO / LAPANOUSE / CIMIER

295	13'''	22
294	10 1/2'''	120
294	10 1/2'''	123 = 120
451	10 1/2'''	125
425	13'''	130
425	13'''	132 = 130
425	13'''	133 = 130
425	13'''	140 = 130
425	13'''	142 = 130
425	13'''	143 = 130
425	13'''	144 = 130
425	13'''	146 = 130
425	13'''	147 = 130
451	10 1/2'''	152 = 125
508	12'''	153
1023	6 3/4-8'''	180
1023	6 3/4-8'''	182 = 180
296	9 3/4'''	201 ord. & KIF
1252	9 3/4'''	271
1683	11 1/2'''	272
423	8 3/4'''	301
423	8 3/4'''	302 = 301
423	8 3/4'''	303 = 301
706	8 3/4'''	311

for REVUE, SOLA

504	19'''	30
471	19'''	30 Breguet
297	8 3/4'''	42
977	9 3/4'''	50
476	10 1/2'''	56
298	12'''	59
598	12'''	59 Inca
786	5 1/4'''	61
299	9-12'''	69
787	10 1/2'''	76
788	10 1/2'''	76 Inca
300	11 1/2'''	77
596	11 1/2'''	77 Inca
1317	8 3/4'''	78
860	13'''	81
1303		84
1349	5 1/2'''	205

• annulaire, schraubenlos, screwless, sin tornillos

RENATA - O mais importante produtor de balanços completos destinados à montagem de relógios

RENATA

for RONDA, RL

1679	10 ¹ / ₂ '''	1011 à pl. ord. & KIF
1679	10 ¹ / ₂ '''	1013 à pl. ord. & KIF = 1011
1679	10 ¹ / ₂ '''	1015 à pl. ord. & KIF = 1011
1679	10 ¹ / ₂ '''	1017 à pl. ord. & KIF = 1011
1679	11 ¹ / ₂ '''	1111 à pl. ord. & KIF = 1011
1679	11 ¹ / ₂ '''	1113 à pl. ord. & KIF = 1011
1679	11 ¹ / ₂ '''	1115 à pl. ord. & KIF = 1011
1679	11 ¹ / ₂ '''	1117 à pl. ord. & KIF = 1011
1679	12'''	1211 à pl. ord. & KIF = 1011
1679	12'''	1213 à pl. ord. & KIF = 1011
1679	12'''	1215 à pl. ord. & KIF = 1011
1679	12'''	1217 à pl. ord. & KIF = 1011
1368	7 ³ / ₄ '''	3011 à pl.
1591	7 ³ / ₄ '''	3013 à pl.
1368	7 ³ / ₄ '''	3021 à pl. = 3011
1211	5 ¹ / ₄ '''	4011 à pl.
1313	6 ³ / ₄ -8'''	5001 à pl.
1313	6 ³ / ₄ -8'''	5011 à pl. = 5001
1313	6 ³ / ₄ -8'''	5021 à pl. = 5001
1313	8'''	5111 à pl. = 5011
1313	8 ³ / ₄ '''	5211 à pl. = 5011
1313	8 ³ / ₄ '''	5221 à pl. = 5001
1322	8 ³ / ₄ '''	6013 à pl.
1322	9 ³ / ₄ '''	6113 à pl. = 6013
1314	10 ¹ / ₂ '''	6213 à pl.
1314	11 ¹ / ₂ '''	6313 à pl. = 6213
1367	10 ¹ / ₂ '''	7011 à pl.
1367	10 ¹ / ₂ '''	7013 à pl. = 7011
1574	10 ¹ / ₂ '''	7013 à dgt.
1367	10 ¹ / ₂ '''	7015 à pl. = 7011
1367	11 ¹ / ₂ '''	7111 à pl. = 7011
1367	11 ¹ / ₂ '''	7113 à pl. = 7011
1367	11 ¹ / ₂ '''	7115 à pl. = 7011
1458	8 ³ / ₄ '''	8011
1653	8 ³ / ₄ '''	8011 KIF
1458	8 ³ / ₄ '''	8013 = 8011
1653	8 ³ / ₄ '''	8013 KIF = 8011 KIF
1458	8 ³ / ₄ '''	8015 = 8011
1653	8 ³ / ₄ '''	8015 KIF = 8011 KIF
1458	8 ³ / ₄ '''	8021 = 8011
1653	8 ³ / ₄ '''	8021 KIF = 8011 KIF
1458	8 ³ / ₄ '''	8023 = 8011
1653	8 ³ / ₄ '''	8023 KIF = 8011 KIF
1458	8 ³ / ₄ '''	8025 = 8011
1653	8 ³ / ₄ '''	8025 KIF = 8011 KIF

for ROSEBA / RW

301	10 ¹ / ₂ '''	8 à dgt.
441	10 ¹ / ₂ '''	8 à pl.
373	10 ¹ / ₂ '''	50 à dgt.
372	10 ¹ / ₂ '''	50 à pl.
302	10 ¹ / ₂ '''	53 à dgt.
303	10 ¹ / ₂ '''	53 à pl.
302	10 ¹ / ₂ '''	55 à dgt. = 53 à dgt.
303	10 ¹ / ₂ '''	55 à pl. = 53 à pl.
304	8 ³ / ₄ '''	64 à dgt.
305	8 ³ / ₄ '''	64 à pl.
304	8 ³ / ₄ '''	65 à dgt. = 64 à dgt.
305	8 ³ / ₄ '''	65 à pl. = 64 à pl.
304	8 ³ / ₄ '''	66 à dgt. = 64 à dgt.
305	8 ³ / ₄ '''	66 à pl. = 64 à pl.
867	5 ¹ / ₄ '''	72 à pl.
867	5 ¹ / ₄ '''	75 à pl. = 72 à pl.

for ROSKOPF PATENT NATIONAL

526	16'''	16/10
-----	-------	-------

for SEFEA voir JUDEX

for SEIKO

•1593	66 sans vis
•1593	6601 sans vis = 66 310660
•1594	7625 sans vis 310820

for SMITH

1246	8 ³ / ₄ '''	LY shockproof
1250	10 ¹ / ₂ '''	NP Shock
1294	10 ¹ / ₂ '''	TY old ord. & shockproof
1294	10 ¹ / ₂ '''	101 ord. & shockproof = TY old
1250	10 ¹ / ₂ '''	102 TY new shockproof = NP Shock
1046	13'''	RY 144
1175	13'''	RY 144 shockproof
969	8 ³ / ₄ '''	P 314
970	12'''	A 360
1535	10 ¹ / ₂ '''	603 Ingersoll Elite Rosk.

for STANDARD, ST.

•1155	6 ³ / ₄ -8'''	69 sans vis
•1138	6 ³ / ₄ -8'''	69 Inca KIF sans vis
•1509	6 ³ / ₄ -8'''	69-21 ord. & Inca sans vis
•1268	11 ¹ / ₂ '''	96 ord. & Inca sans vis
•1268	11 ¹ / ₂ '''	96-4 ord. & Inca sans vis = 96
•1687	11 ¹ / ₂ '''	97 ord. & Inca sans vis
•1509	6 ³ / ₄ -8'''	608-21 ord. & Inca sans vis = 69-21

• annulaire, schraubenlos, screwless, sin tornillos

RENATA – der Welt grösster Produzent regulierter Unruhen für Reparaturzwecke

RENATA

for STANDARD, ST.

•1268	11 ¹ / ₂ '''	969 ord. & Inca sans vis = 96
•1268	11 ¹ / ₂ '''	969-4 ord. & Inca sans vis = 96
•1115	11 ¹ / ₂ '''	1686 ord. Inca KIF M RS sans vis
•1115	11 ¹ / ₂ '''	1786 ord. Inca KIF M RS sans vis = 1686
•1115	11 ¹ / ₂ '''	1795 ord. Inca KIF M RS sans vis = 1686
•1508	10 ¹ / ₂ '''	1800 ord. & Inca sans vis
•1508	10 ¹ / ₂ '''	1801 ord. & Inca sans vis = 1800
•1508	11 ¹ / ₂ '''	1802 ord. & Inca sans vis = 1800
•1508	11 ¹ / ₂ '''	1803 ord. & Inca sans vis = 1800
•1508	11 ¹ / ₂ '''	1804 ord. & Inca sans vis = 1800
•1508	11 ¹ / ₂ '''	1805 ord. & Inca sans vis = 1800
•1688	10 ¹ / ₂ '''	1940 ord. & Inca sans vis
•1688	10 ¹ / ₂ '''	1941 ord. & Inca sans vis = 1940
•1688	11 ¹ / ₂ '''	1950 ord. & Inca sans vis = 1940
•1688	11 ¹ / ₂ '''	1951 ord. & Inca sans vis = 1940

for TISSOT (suite)

669	8 ³ / ₄ -12'''	20 mm
307	9 ³ / ₄ '''	21.7
307	9 ³ / ₄ '''	21.9 = 21.7
877	12'''	27 Breguet
308	12'''	27
582	12'''	27 Inca
352	12'''	27 B
576	12'''	27 B Inca
575	12'''	27 Shock Resist
308	12'''	27 T = 27
582	12'''	27-1 Inca = 27 Inca
308	12'''	27-2 = 27
575	12'''	27-3 S.R. = 27 S.R.
575	12'''	27-7 S.R. = 27 S.R.
575	12'''	27-23 S.R. = 27 S.R.
852	13'''	28.1 Inca
852	13'''	28.5-1 Inca = 28.1 Inca
852	13'''	28.21 Inca = 28.1 Inca
852	13'''	28.5-21 Inca = 28.1 Inca
852	13'''	31.1 Inca = 28.1 Inca
853	18'''	38.2
309	19'''	40.5
343	19'''	43
•1242	5 ¹ / ₂ '''	709 ord. & Inca sans vis
•1243	11 ¹ / ₂ '''	781 ord. & Inca sans vis
•1243	11 ¹ / ₂ '''	782 ord. & Inca s. vis = 781
•1243	11 ¹ / ₂ '''	783 ord. & Inca s. vis = 781
•1243	11 ¹ / ₂ '''	784 ord. & Inca s. vis = 781

for ULTRA

1157	10 ¹ / ₂ '''	602
------	------------------------------------	-----

for UNITAS / UT

806	17 ³ / ₄ '''	87
806	17 ³ / ₄ '''	88 = 87
310	10 ¹ / ₂ '''	148 bas
310	10 ¹ / ₂ '''	150 bas = 148 bas
310	10 ¹ / ₂ '''	156 bas = 148 bas
428	13'''	173
311	13'''	174
312	13'''	176
578	13'''	176 Inca
312	13'''	177 = 176
578	13'''	177 Inca = 176 Inca
312	13'''	178 = 176
578	13'''	178 Inca = 176 Inca
312	13'''	179 = 176
578	13'''	179 Inca = 176 Inca
313	10 ¹ / ₂ '''	186
871	10 ¹ / ₂ '''	186 Inca
313	10 ¹ / ₂ '''	187 = 186
871	10 ¹ / ₂ '''	187 Inca = 186 Inca

for STUDIO voir Vulcain

667	5 ¹ / ₄ '''	43
518	10 ¹ / ₂ '''	65 S. P.

for TECHNIC-EBAUCHE M.P.

987	5 ¹ / ₄ '''	10
•1191	5 ¹ / ₄ '''	S 54 sans vis
1618	5 ¹ / ₂ '''	S 73 A ord. & Inca

for TISSOT

908	5-6 ³ / ₄ '''	11.7 Glucydur
1077	5-6 ³ / ₄ '''	11.7 Inca Glucydur
718	5 ¹ / ₄ '''	12.6
620	5 ³ / ₄ -7'''	13.6
663	6 ³ / ₄ -8'''	15.3
819	7 ³ / ₄ -9 ¹ / ₂ '''	17.5-1 Inca Glucydur
854	8 ³ / ₄ '''	19.4

• annulaire, schraubenlos, screwless, sin tornillos

RENATA - le producteur le plus important du monde de balanciers réglés destinés aux rhabillages

RENATA

for UNITAS / UT (suite)

350	6 ³ / ₄ '''	190	
745	6 ³ / ₄ '''	190	Inca
350	6 ³ / ₄ '''	192	= 190
745	6 ³ / ₄ '''	192	Inca = 190 Inca
350	6 ³ / ₄ '''	195	= 190
745	6 ³ / ₄ '''	195	Inca = 190 Inca
313	10 ¹ / ₂ '''	196	= 186
871	10 ¹ / ₂ '''	196	Inca = 186 Inca
313	10 ¹ / ₂ '''	197	= 186
871	10 ¹ / ₂ '''	197	Inca = 186 Inca
313	10 ¹ / ₂ '''	198	= 186
871	10 ¹ / ₂ '''	198	Inca = 186 Inca
313	10 ¹ / ₂ '''	199	= 186
871	10 ¹ / ₂ '''	199	Inca = 186 Inca
314	8 ³ / ₄ '''	200	
577	8 ³ / ₄ '''	200	Inca
314	8 ³ / ₄ '''	201	= 200
577	8 ³ / ₄ '''	201	Inca = 200 Inca
314	8 ³ / ₄ '''	202	= 200
577	8 ³ / ₄ '''	202	Inca = 200 Inca
312	13'''	204	= 176
578	13'''	204	Inca = 176 Inca
312	13'''	205	= 176
578	13'''	205	Inca = 176 Inca
312	13'''	206	= 176
578	13'''	206	Inca = 176 Inca
312	13'''	207	= 176
578	13'''	207	Inca = 176 Inca
312	13'''	228	= 176
578	13'''	228	Inca = 176 Inca
1195	18 ¹ / ₂ -21'''	233	
1195	18 ¹ / ₂ -21'''	241	= 233
840	18 ¹ / ₂ '''	245	
840	18 ¹ / ₂ '''	251	= 245
840	18 ¹ / ₂ '''	261	= 245
840	18 ¹ / ₂ '''	267	= 245
840	18 ¹ / ₂ '''	273	= 245
840	18 ¹ / ₂ '''	279	= 245
348	16 ¹ / ₂ -17 ³ / ₄ '''	285	
348	16 ¹ / ₂ -17 ³ / ₄ '''	286	= 285
806	17 ³ / ₄ '''	287	= 87
348	16 ¹ / ₂ -17 ³ / ₄ '''	293	= 285
806	17 ³ / ₄ '''	295	= 87
348	16 ¹ / ₂ -17 ³ / ₄ '''	299	= 285
348	16 ¹ / ₂ -17 ³ / ₄ '''	303	= 285
806	17 ³ / ₄ '''	307	= 87
348	16 ¹ / ₂ -17 ³ / ₄ '''	327	= 285
348	16 ¹ / ₂ -17 ³ / ₄ '''	331	= 285
348	16 ¹ / ₂ -17 ³ / ₄ '''	335	= 285
348	16 ¹ / ₂ -17 ³ / ₄ '''	339	= 285
806	17 ³ / ₄ '''	341	= 87
348	16 ¹ / ₂ -17 ³ / ₄ '''	345	= 285
348	16 ¹ / ₂ -17 ³ / ₄ '''	348	= 285
806	17 ³ / ₄ '''	349	= 87

for UNITAS / UT (suite)

806	17 ³ / ₄ '''	351	= 87
806	17 ³ / ₄ '''	353	= 87
806	17 ³ / ₄ '''	355	= 87
312	13'''	376	= 176
578	13'''	376	Inca = 176 Inca
1135	18 ¹ / ₂ -19'''	428	
1135	18 ¹ / ₂ -19'''	429	= 428
840	18 ¹ / ₂ '''	431	= 245
840	18 ¹ / ₂ '''	435	= 245
840	18 ¹ / ₂ '''	439	= 245
1195	18 ¹ / ₂ -21'''	443	= 233
840	18 ¹ / ₂ '''	445	= 245
840	18 ¹ / ₂ '''	451	= 245
840	18 ¹ / ₂ '''	455	= 245
840	18 ¹ / ₂ '''	473	= 245
840	18 ¹ / ₂ '''	479	= 245
1195	18 ¹ / ₂ -21'''	481	= 233
806	17 ³ / ₄ '''	490	= 87
806	17 ³ / ₄ '''	493	= 87
348	16 ¹ / ₂ -17 ³ / ₄ '''	497	= 285
348	16 ¹ / ₂ -17 ³ / ₄ '''	498	= 285
312	13'''	500	= 176
578	13'''	500	Inca = 176 Inca
316	5 ¹ / ₄ '''	510	
592	5 ¹ / ₄ '''	510	Inca
316	5 ¹ / ₄ '''	520	= 510
592	5 ¹ / ₄ '''	520	Inca = 510 Inca
316	5 ¹ / ₄ '''	521	= 510
592	5 ¹ / ₄ '''	521	Inca = 510 Inca
316	5 ¹ / ₄ '''	523	= 510
592	5 ¹ / ₄ '''	523	Inca = 510 Inca
317	5 ¹ / ₄ '''	525	
500	5 ¹ / ₄ '''	530	
315	6 ³ / ₄ -8'''	540	
1120	6 ³ / ₄ -8'''	540	Inca
315	6 ³ / ₄ -8'''	541	= 540
315	6 ³ / ₄ -8'''	542	= 540
1120	6 ³ / ₄ -8'''	550	Inca = 540 Inca
313	10 ¹ / ₂ '''	560	= 186
871	10 ¹ / ₂ '''	560	Inca = 186 Inca
753	8 ³ / ₄ '''	580	
749	13 ³ / ₄ '''	600	
749	13 ³ / ₄ '''	607	= 600
749	13 ³ / ₄ '''	610	= 600
749	13 ³ / ₄ '''	620	= 600
1121	8 ³ / ₄ '''	630	
•1455	8 ³ / ₄ '''	630	sans vis
1374	8 ³ / ₄ '''	630	Inca
•1456	8 ³ / ₄ '''	630	Inca sans vis
1241	13'''	640	
1397	13'''	640	Inca
1241	13'''	650	= 640
1397	13'''	650	Inca = 640 Inca
•1411	13'''	6300	sans vis

• annulaire, schraubenlos, screwless, sin tornillos

RENATA – The world's greatest producer of adjusted balances for repair purposes